

MINING INDUSTRY



Mineral production requires a series of physical and chemical processes. These can take place at any time, from the excavation of the ore containing the metal in mineral form, to the transformation of the metal. WeeSafe offers a range of short-use garments for the mining industry.

HAZARDOUS PRODUCTS - MINING INDUSTRY

HAZARDOUS PRODUCTS IN LIQUID OR DRY FORM	WORKS	Wee Cover	Wee Pro
CRYSTALLINE SICILY	Excavation.	⊘	8
COAL DUST	Excavation.	⊘	×
ARSENIC	Excavation.	⊘	×
COBALT	Excavation.	⊘	8
PLOM	Excavation.	⊘	×
MISCELLANEOUS SOLVENTS	Solvent extraction.	8	⊘
SULPHURIC ACID	Extraction by fusion of ores. Leaching: extraction process.	8	⊘
HYDROFLUORIC ACID	Analysis of samples taken during exploration drilling.	×	⊘





Type 5/6 coverall

Protection against all hazardous fine dusts. Can be worn during excavation phases to protect against large quantities of suspended dust, including crystalline silica. Its loose fit and Jersey cuffs provide the operator with absolute comfort.







REFERENCE	SIZE
WL-C-02	М
WL-C-03	L
WL-C-04	XL
WL-C-05	XXL
WL-C-06	XXXL

- Antistatic treatment on both sides (internal and external)
- Zipper with self-adhesive flap
- Waterproof heat-sealed seams
- 3-piece hood for a perfect fit to the protective mask
- Elasticated thumb loop for junction with gloves
- · Breathable material for greater comfort



Type 5/6 coverall

Optimal protection against splashes of liquid products with low chemical concentration. It is also worn during beneficiation (mineral separation process) to protect against the various chemical products used.







REFERENCE	SIZE
WL-P-01	S
WL-P-02	М
WL-P-03	L
WL-P-04	XL
WL-P-05	XXL
WL-P-06	XXXL

- Antistatic treatment on both sides (internal and external)
- Zipper with self-adhesive flap
- 3-piece hood for a perfect fit to the protective mask
- Jersey cuff which ideally replaces the tightening elastic
- Breathable material for more comfort
- Collar version also available

UNDRESSING, A RISKY MOMENT

When short-use protective suits are used, there is a high risk of contamination during the operation and when undressing.

The wearer must carefully adjust the suit at the hood, wrists and ankles. When undressing, a strict procedure must be followed to avoid any contact with the outside of the suit.



Medicom SAS, Boulevard de la Chanterie, 49124 Saint-Barthélemy-d'Anjou I France



